FREDERICK-FIRESTONE FIRE PROTECTION DISTRICT



Community Risk Reduction Planning Section

Office: (303) 833-2742 Fax: (303) 833-3736 E-Mail: <u>siacino@fffd.us</u>

dpuccetti@fffd.us jvenerable@fffd.us

Annual Business Fire Safety Inspection Fact Sheet

What is an Annual Business Fire Safety Inspection?

Every business within the District will receive an annual Fire Safety Inspection from Frederick-Firestone Fire Protection District staff. The purpose of the inspection is to ensure that your business is kept in a safe condition for you, your employees, and your customers.

Will I be notified?

Not always. But, you are always able to schedule your inspection with us at a time that is convenient for you.

What will the inspection consist of?

There are many common safety issues that we find when reviewing businesses in the area, and most are simply oversights that you may not consider. The Fire Safety Inspection will be completed using the current edition of the International Fire Code adopted by the Town of Frederick and the Town of Firestone. A list of the most common fire safety issues are listed below.

What will happen if I have a fire code violation?

If a fire code violation(s) is identified during your Fire Safety Inspection, you will be given two-weeks to get the fire code violation(s) corrected. At the time of the first inspection, the second fire code re-inspection will be scheduled.

At the second Fire Safety Inspection, it will be verified that the fire code violation(s) was corrected. If the fire code violation(s) has not be corrected, another re-inspection will be scheduled at a fire code inspection rate of \$88.00. This inspection rate will continue with all additional inspections that have to be scheduled.

In the event the fire code violation continues, a municipal summons may be issued to ensure the fire code violation(s) are corrected.

Additional Questions?

We want to help you and our community be a as fire aware and fire safe as possible and assist you in your continued success in our community. If you have additional questions, please contact our Administration Offices at 303-833-2742, Monday through Thursday between the hours of 8 a.m. and 4:30 p.m.

Thank you,

Steve lacino

Assistant Chief/Fire Marshall Frederick Firestone Fire Protection District

Some common fire safety issues previously found in area businesses that you should check in your own business include:

Business Exterior	
	Fire hydrant(s) must have 36" of unobstructed clearance on all sides.
	The building/unit address must be clearly visible from the street/nearest approach
	The means of access to the property must be free of obstruction for
	access by emergency vehicles
	An approved Knox Box must be provided on the exterior of the building and contain a labeled master key that will access exterior
	doors of the entire building/unit.
Signage	
	The Occupancy Load for the business/area must be posted. If required
Exits and Stairwells	1
П	The minimum exit width is 36". Obstruction to exits shall not be
	placed in the required width and exits shall not be obstructed in any
	, , , , , , , , , , , , , , , , , , ,
	The means of egress, including the exit, shall be illuminated at all
	times that the building space is occupied
Electrical and gas appliance	
	36" of clear space must be maintained around all electrical panels,
	disconnects, and all gas appliances.
	Improper use of extension cords – Extension cords cannot be used in
	place of permanent wiring. Only one UL listed 6' power strip is
	allowed per electrical outlet.
Fire Extinguishers	
	All fire extinguishers must be properly stored and mounted between
	3' to 5' from the floor.
	All fire extinguishers must be properly inspected and properly tagged
	by a licensed inspector annually.
	Kitchen hood fire suppression systems must be tested and inspected
_	every six months.
	NOTE: If you or your staff is interested in fire extinguisher training
	please visit our website at www.fffd.us . Go to the Community
	Involvement Icon, select Education Programs, and select Fire
	Extinguisher Training – Online.
П	For further information or questions that you or your staff have
	regarding fire extinguishers please feel free to ask the firefighters
	during your annual fire code inspection.
T' 41 C '11 0 C	1: 0 .
Fire Alarm, Sprinkler & Sta	2 2 · ·
	Clear access to operation of all valves must be maintained
	All sprinkler heads shall be free of paint
	Storage shall be 2 feet or more below the ceiling in non-sprinklered
	areas of buildings or a minimum of 18" below sprinkler head in
	sprinkled areas of buildings.
	Storage in open areas shall not exceed 20 feet in height.
	All fire alarm systems, fire sprinkler systems, backflow preventers
	and other fire suppression systems must be inspected by a qualified
	technician annually.

Storage of Combustibles and Flammables	
	All combustible liquids must be stored in a UL listed storage cabinet
	All flammables and combustibles must be kept away from all ignition
	sources.
	All flammable and combustible storage containers must be sealed and
	labeled as to their contents
Fire Resistive Construction	
	Fire doors and assemblies shall not be modified
	Fire doors and smoke barriers doors shall not be blocked or obstructed or
	otherwise made inoperable. No door wedges or fold feet are allowed in
	rated corridors. NOTE: This only applies to non-fire sprinkler
	assemblies
	Swinging fire doors shall close from the fully open position and latch
	automatically. The door closer shall exert enough to close and latch the
	door from nay partial open position
	Horizontal and vertical sliding and rolling fire doors shall be inspected
	and tested annually to confirm proper operation and full closure. A
	written record shall be maintained and be available for review
	When magnetic hold-open devices on fire doors are out of service the
	door shall remain I the closed position
	Curtains, draperies, hangings and other decorative materials suspended
	from walls or ceilings shall be flame resistant. This is to include all
	furniture and fabric materials
	Fire-resistive assemblies including drywall, masonry brick, roof
	assemblies and ceiling tile shall in good repair.
	Openings through fire-resistive assemblies shall be protected by self-
	closing or automatic closing doors